Cannot output sound on Windows PC

If you make connection to a Windows PC with following products, audio sometimes will not be output under the following conditions.

* H2n/H3-VR/H4nPro/H5/H6/F4/F6/F8/F8n

1. Products are connecting by "ZOOM H and F Series Audio Driver" to a Windows PC.
2. The buffer size of "ZOOM H and F Series Audio Driver" set at 64 or 128 on DAW.

When you experience this problem, the following workaround may be effective:

* When using the ZOOM H and F Series Audio Driver on DAW, select the buffer size other than 64 or 128.

Example - Cubase LE

Open "ZOOM H and F Series ASIO" tab and click "Control Panel".

Change Buffer Size to other than 64 or 128.

We apologize for any inconvenience caused.