


F8n MultiTrack Field Recorder System Software Version History



https://zoomcorp.com/

Version 2.40

shown below.

- Released as the following bug fix in March 2022
- 1. F8n does not boot up in some rare instances.

Version 2.30

- Released as the following bug fix in July 2021
- 1. HPF settings cannot be set correctly for stereo-linked inputs from F8 Control app on iOS/iPadOS.

Version 2.20

- · Released as the following bug fix in April 2021
- 1. No sound is output when "SUB OUT Routing" assigns Tracks 1-4 to SUB OUT 1 once F8n is used in audio interface mode.

Version 2.10

- Released as the following bug fixes in September 2019
- 1. F8n cannot connect to iOS devices in iOS 13 / iPadOS 13 via Bluetooth.
- 2 Noise is heard after FRC-8 is disconnected

Version 2.00

Released as the following bug fix and function update in June 2019

■Function Update

1. Added a function to receive timecode over Bluetooth LE from UltraSync BLUE by Timecode Systems and write timecode information to a recording file.

Installation of the software extension file is required to use Bluetooth LE function.

■Bug Fix

1. The time reference of recorded files is slightly shifted when the frame rate for timecode is set to 29 97D

Version 1.20

· Released as the bug fixes in November 2018

Version 1.10

Released as the bug fix and function update in July 2018

Version 1.00 Z2I-3421-07

Released as mass production in June 2018