
L-20 Software Version History



Version 1.14

- Released as following bug fixes in January 2020
- 1. No pop-up message is shown telling the operation is disabled when the sample rate is set to 96kHz and some functions are not available.
- 2. No pop-up message is shown telling the operation is disabled when used in the card reader mode and some functions are not available

Version 1.02

- Released as following bug fix in August 2018
- 1. L-20 internal clock sometimes does not work.

Version 1.00

· Released as mass production in July 2018