

Faults and workaround on OS older than Mac OSX 10.8.5 for UAC Series.

July, 2016

After Mac wakes up from Sleep mode, no audio signal is output from UAC-series interfaces when running OS is older than Mac OSX 10.8.5

If this problem occurs, please update to a later version of Mac OSX as this fault will not occur when running OS is newer than Mac OSX 10.9